

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Justin Burch
Inspection Date:	Saturday, July 14, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☒ Trench Excavation

☒ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Bore Pit Excavation

- | | | Yes | No | N/A |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Location: Station 14010+00 to Station 14019+00

All controls were in place and in good condition with upgraded or additional measures with the exception that the three waterbars were mostly eliminated with large bore pit excavation. After the bore pit is backfilled three waterbars will be re-established.

Offsite sediment was observed at station 14017+80 on the right side which, according to Tracy Hilbun, happened before the perimeter control was upgraded to super silt fence.

Inspector Justin Burch's judgement is that this area passes inspection.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Justin Burch Date: 7-14-2018

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Saturday, July 14, 2018

Fig. 1 CWD Plunge Pool



Fig. 2 Large Bore Pit partially excavated




Fig. 3 Stockpile Stabilization & Perimeter Controls



Fig. 4 RCE at Bonbrook Mill Rd

